



Illustration 1: Return line is visible. Electric tape holds the sensor wires against the lines

Sandy's photos



Illustration 2: This tall silver maple shades the collectors after 2 p.m. ...but not for much longer.



Illustration 3: Another view of tree shading. Photo taken about 3-4 pm. These trees are beautiful, but they are too large and too close to my and my neighbour's houses should they come down in a windstorm. The collectors are hidden behind the lilac bush lower right.



Illustration 4: Close up of sun face icon and wiring loom (corrugated plastic auto wiring loom).



Illustration 5: View of feed and return lines. Fenders from a 72 Olds Cutlass (another project) in the background.



Illustration 6: I decided to store the unused fiberglass batts on the tank....this should increase the R-value of the lid!

